

Spring Lake Improvement District Equipment Evaluation  
January 2022

ID TAG	MAKE	COLOR	Serial/VIN #	YEAR	Hours	Condition	Type Svc.	Reliability	Total Repair	Total
4762	Niftylift	Green	SLN34MG00MM044762	2021	N/A	1	1	1	0	3
0091	Bad Boy mower	Orange	BRG6135KA06200091	2020	458	4	5	3	4	16
0088	Bad Boy mower	Orange	BRG6135KA06190088	2019	501	4	5	3	4	16
3676	Hustler Parks Mower	Yellow	14053676	2014	1,573	5	5	2	1	13
1114	Hustler Parks Mower	Yellow	16111114	2017	728	2	5	1	1	9
3006	EZ Go golf cart	Green	2533006	2007	N/A	5	3	3	2	13
3007	EZ Go golf cart	Green	2533007	2007	N/A	5	3	3	2	13
0733	John Deere Gator 4x4	Green	1M0825SMALLM030733	2020	817	2	5	1	1	9
0708	John Deere Gator 4X4	Green	1M0825GSEGM110708	2015	1,800	3	5	1	1	10
0166	John Deere Gator 4X4	Green	1M0825GSEBM040166	2011	2,841	3	5	1	2	11
3953	John Deere 6155 Tractor #2	Green	1L06155MEMH103953	2020	808	1	5	1	0	7
0148	John Deere 6155 Tractor # 1	Green	1L06155MCJH920148	2019	2,148	1	5	1	1	8
7710	John Deere 6125 Tractor # 3	Green	1L06125MHFH827710	2015	4,377	4	5	1	2	12
1153	Rhino 15' batwing mower used on #3 tractor	Red	41153	2020	N/A	1	5	1	0	7
0447	Rhino 15' batwing mower used on #2 tractor	Red	40447	2019	N/A	2	5	1	1	9
0625	Rhino 15' batwing mower used on #1 tractor	Red	30625	2017	N/A	5	5	4	5	19
0025	Challenger Boom Mower	Yellow	66620025	2013	3,916	2	5	2	2	11
3553	Caterpillar 420F IT Backhoe	Yellow	CAT0420FPHWD03553	2019	344	2	5	1	1	9
0260	Caterpillar 420F Backhoe	Yellow	CAT0420FHHWD00260	2015	1,542	2	5	1	2	10
0367	Hydrema Dump Truck	Yellow	10367	2011	2,889	3	5	1	1	10
1290	Caterpillar 320 Trackhoe	Yellow	SPN01290	2012	3,110	3	5	1	1	10
118K	8" Diesel pump	Black	AM36995 / W542118K	2003	6,129	3	3	1	3	10
3799	Carolina Skiff spray boat	White	165920M05053799	2011	N/A	1	3	1	1	6
	8,000 watt Norther Generator			2005	N/A	3	5	2	2	12
5334	65kw Tradewinds generator / Lift Station	White	5334	2020	50	2	1	3	1	7
1027	600kw Tradewinds generator / Pump Station	White	1027	2018	167	1	1	1	1	4
4167	299D Skid steer	Yellow	CAT0299DCFD204167	2018	482	1	5	1	1	8
	#3 3406 CAT pump motor	Yellow	90U496	1978	586	2	3	1	1	7
	#4 3406 CAT pump motor	Yellow	90U491	1978	574	2	3	1	1	7
<b>Utilities</b>										
	Vector Vactron	Yellow	1V9PT2125A109003	2002	372	5	5	4	3	17
	Skil 14" Concrete Saw	Orange	172109520	2010	N/A	1	1	1	1	4
	3" Mud Hog water pump	Blue	502216	2017	N/A	1	5	1	1	8
	3" Mud Hog water pump	Blue	502217	2017	N/A	1	5	1	1	8
	Thompson pump	Blue	2181358-21	2018	620	1	3	1	1	6
	#1 Bearcat generator	Red	T6450016110109380	2018	42	1	1	1	1	4
	#2 Bearcat generator	Red	T6450016110109375	2018	26	1	1	1	1	4
	Kohler generator/ Sewer Plant	Tan	3346GMGH0050	2019	84	1	2	1	1	5

**Point Ranges for Replacement Consideration**

1-5 Points	Condition I: Excellent
6-10 Points	Condition II: Good
11-15 Points	Condition III: Qualifies for Replacement
16 and above	Condition IV: Needs Immediate Consideration

Note: It is my recommendation that both bad boy mowers be replaced. Reason due to a constant effort to keep them in working order due excessive break downs.  
Note: It is also my recommendation to replace the oldest batwing mower. It is just wore out due to normal use. Wear and tear.